

interphone

F5MC firmware release note

Rev.	Date	Description
R106	25 Feb 2015	<ul style="list-style-type: none">• Mod: new improved noise suppression.• Mod: changed low battery warning timeout to 20 minutes and very-low battery to 5 minutes.
R104	20 Jun 2014	<ul style="list-style-type: none">• Mod: increased FM radio receiver sensitivity.
R102	23 May 2014	<ul style="list-style-type: none">• Fix: bug fix for microphone muted, when incoming phone call during FM radio listening.
R100	13 May 2014	<ul style="list-style-type: none">• Mod: improved noise suppression.• Mod: changed sensitivity of automatic volume control.• Mod: vocal help now stops during phonecall ringtone.• Mod: erasing pairing (from setup menu) now will end with unit in pairing mode.• Mod: with unit off, now is possible to select the language, powering on the unit and keep pressed MFB (as previous XT range).• Fix: bug fix with Czeck lang.• Fix: fixed error message for intercom connection when only one another unit is paired.• Fix: minor bugfix.
R91/R91C	03 Mar 2014	<ul style="list-style-type: none">• Fix: minor bugfix.